






STEP:1




STEP:2



STEP:3



STEP:4



|                               |                    |                               |                                    |                               |
|-------------------------------|--------------------|-------------------------------|------------------------------------|-------------------------------|
| <b>①</b><br><br>x1            | <b>②</b><br><br>x2 | <b>③</b><br><br>x2            | <b>④</b><br><br>x1                 | <b>⑤</b><br><br>x1            |
| <b>A</b><br><br>M6x16mm<br>x8 | <b>B</b><br><br>x1 | <b>C</b><br><br>M6x30mm<br>x4 | <b>D</b><br><br>M6xΦ16x2.0mm<br>x4 | <b>E</b><br><br>M6x18mm<br>x4 |