



1 357-000019




2


Step 2 : 80% tighten screw at this stage.






3 Step 3 : After all parts are in right position, then 100% tighten up all screws before using.



4



A  x4	B  x4	C  x8	D  x4	E  x4	F  x1	G  x1	H  x1
--	--	--	--	--	---	--	--