



1 357-000020




2


Step 2 : 80% tighten screw at this stage.



3 Step 3 : After all parts are in right position, then 100% tighten up all screws before using.



4



A	B	C	D	E	F	G	H
x4	x4	x8	x4	x4	x1	x1	x1