











1  x1	2  x1	3  x1	4  x1	5  x1	6  x1
7  x1	8  x1	9  x3	10  x2	11  x1	A  x10
B  x10	C (6.3X50mm)  x38				

Step 1



A x2


Step 2



A x6


B x4

Step 3



C x2


Step 4



B x4


C x2

Step 5




C x4

Step 6



C x2


Step 7



A x2


B x2

Step 8




C x4

Step 9



C x12

Step 10



C x12

Complete

