





















1  x1	2  x1	3  x1	4  x1	5  x1
6  x1	7  x1	8  x1	9  x1	10  x1
11  x2	12  x1	13  x1	14  x1	15  x1
16  x1	17  x1	18  x1	A  x32 B  x32	
D  x6	E  x3	F (3.5x12mm)  x48	C (6.3x50mm)  x13	

Step 1




A	x4
B	x4

Step 2




C	x8
---	----

Step 3




Step 4




A	x8
B	x8

Step 5




A	x8
B	x8

Step 6




A	x4
B	x4

Step 7




A	x8
B	x8

Step 8



D	x6
F	x36

[illegible]

Step 10

Diagram illustrating Step 10 of the assembly process. A panel (18) is being attached to a bracket (16, 17) using four screws (C). The screws are shown being inserted into the panel and the bracket.

C	x5
---	----

Complete