










230-000184

1 	2 	3 	4 	5 
X1	X1	X1	X1	X1
6 	7 	A 	B 	C (6.3X50) 
X1	X1	X12	X12	X6

Step 1

An isometric diagram showing the assembly of a rectangular frame. A horizontal plate (1) is being attached to a vertical plate (4) using four screws (A+B). A small circular component (2) is positioned on the horizontal plate. The screws are shown in the process of being inserted into the pre-drilled holes in the plates.

A	x4
B	x4

Step 1



An isometric diagram showing the assembly of a rectangular frame. A horizontal plate (1) is being attached to a vertical plate (4) using four screws (A+B). A small circular component (2) is positioned on the horizontal plate. The screws are shown in the process of being inserted into the pre-drilled holes in the plates.

A	x4
B	x4

Step 1

An isometric diagram showing the assembly of a rectangular frame. A horizontal plate (1) is being attached to a vertical plate (4) using four screws (A+B). A small circular component (2) is positioned on the horizontal plate. The screws are shown in the process of being inserted into the pre-drilled holes in the plates.

C	x6
---	----

Step 3  <table><tr><td>A</td><td>x4</td></tr><tr><td>B</td><td>x4</td></tr></table>	A	x4	B	x4	Complete 
A	x4				
B	x4				