




STEP:1




STEP:2




STEP:3




STEP:4




STEP:5



STEP:6



1




x1

2




x2

3



x1

4



x1

A



M6xΦ18x1.5mm

x8


B



M6x16mm

x2

C



x1

D



M6xΦ16x1.5mm

x2

E



M6x30mm

x2

F



M6x40mm

x2

G



M6x35mm

x4