












1  x1	2  x1	3  x2	4  x1	5  x1	6  x1	
7  x1	8  x1	9  x1	10  x1	11  x1	12  x2	
13  x2	A  x20 B  x20		C (6.3X50)  x6	D (3.5X12)  x12	E  x2	F (4X35)  x12

Step 1




A	x4
B	x4

Step 2




A	x4
B	x4

Step 3




F	x12
---	-----

Step 4




A	x6
B	x6

Step 5




C x6

Step 6



A x6
B x6

Step 7



D x12
E x2

Complete

