




























230-000102

1  x1	2  x1	3  x1	4  x1	5  x1
6  x1	7  x1	8  x1	9  x1	10  x1
11  x1	12  x1	13  x1	14  x1	15  x1
16  x1	17  x1	18  x2	19  x1	20  x1
21  x1	22  x1	23  x1	24  x1	25  x1
26  x1	27  x2	28  x1	29  x1	30  x1
31  x1	A  x61	B  x61	C (6.3x50mm)  x19	D  x7
E  x2	F (3.5x12mm)  x54	G  x4	H  x4	I  x3


Step 1




Step 2




Step 3




Step 4




Step 5




Step 6




Step 7




Step 8




Step 9




Step 10




Step 11



Step 12




Step 13




F	x2
G	x2

Step 14




F	x2
G	x2

Step 15




F	x2
C	x3
G	x2

Complete



Step 16



H	x2
---	----