


















1  x1	2  x1	3  x1	4  x1	5  x1
6  x1	7  x1	8  x1	9  x1	10  x1
11  x1	12  x1	13  x1	14  x1	15  x1
A  x23	B  x23	C (6.3x50mm)  x11	D  x4	E  x2
F (3.5x12mm)  x32	G  x6			

Step 1




A	x3
B	x3

Step 2




C	x6
---	----

Step 3




Step 4




- | | |
|---|----|
| A | x6 |
| B | x6 |

Step 5




- | | |
|---|----|
| A | x7 |
|---|----|

Step 6




- | | |
|---|----|
| B | x7 |
|---|----|

Step 7




- | | |
|---|----|
| A | x7 |
| B | x2 |

Step 8




- | | |
|---|----|
| B | x5 |
|---|----|


Step 9




Step 10



Step 11



Complete



Step 12

