



①




First screw down


②






③



④



⑤

A		4	G		4
B		1	H	 6*14MM	8
C	 10*22*1.5MM	4	I	 6*16*1.0MM	8
D	 10*30MM	4	J		1
E		1	K		4
F		1			