





















| | | |
|---|---|--|
| A  (M6mm) 14PCS | H  (ST6.3X50mm) 10PCS | I  4PCS |
| B1  (M6X35mm) 2PCS |  2PCS |  1PCS |
| B2  (M6X10mm) 5PCS |  2PCS | 1  1PCS |
| B3  (M6X30mm) 4PCS | 2  1PCS | 3  1PCS |
| C  (ST3.5X12mm) 8PCS | 4  1PCS | 5  1PCS |
| D  (ST3.5X25mm) 2PCS | 6  1PCS | 7  1PCS |
| E  2PCS | 8  1PCS | 9  1PCS |
| F  (ST5X50mm) 4PCS | 10  1PCS | 11  1PCS |
| G  (M6mm) 1PCS | 12  1PCS | |




Step 5




Step 6




Step 7



Step 8



Step 9



Step 10

